



**Abbott**

## **IMPORTANT FIELD SAFETY NOTICE**

CentriMag Motors  
Certain Serial Numbers between L05333-0001 and L06608-0024  
Catalog Numbers 201-10002

August 22, 2019

Dear Clinician,

Abbott is advising our customers that we have received reports of CentriMag Systems experiencing motor and pump issues resulting from electromagnetic interference (EMI). Due to this EMI exposure, Customers have experienced unexpected console screen blanking, low flow or no flow, and motor behavior including noise, vibration and heating have been reported at a rate of 0.45%. Our investigation has identified CentriMag Motors with certain serial numbers between L05333-0001 and L06608-0024 with an increased susceptibility to EMI. In a small number of cases, this issue has been associated with serious injuries due to hemodynamic compromise resulting from interruption of support. As explained below, this issue can be mitigated through recalibration of the motor.

### **Patient Management Recommendations**

The CentriMag System includes audio and visual alarms, and the Instructions for Use (IFU) require that a full backup system be in the vicinity of any patient on support.

- Continued use of the motor is acceptable until recalibration can be performed as long as the motor does not exhibit the issues related to EMI.
- In the event of an EMI issue, auditory alarms will alert care-givers of the problem
- Should an EMI issue occur, switch the pump to the backup system as described in the CentriMag System Operating Manual.

### **Actions that can mitigate electromagnetic interference (EMI)**

The 2nd Generation CentriMag® System Operating Manuals PL-0280 (OUS) provides the following Electromagnetic interference (EMI) considerations and warning:

- Electromagnetic interference (EMI) sources in the vicinity of the System may interfere with Console performance. If changes occur in the operating parameters of the Console due to EMI sources, immediately remove the source of EMI or move the Console away from the source of the EMI.
- The 2nd Generation CentriMag Primary Console may interfere with the operation of other equipment in close proximity.
- Do not place equipment, other than an additional 2nd Generation Primary CentriMag Console, near the main Console or Motor.
- Insert the cord into the AC wall outlet only. Do not use power strips and socket extensions. In the BVAD configuration both Console power cords must be inserted directly into an AC wall outlet.

Abbott has implemented changes to the motor calibration process in manufacturing to mitigate the issue. The updated calibration process was used to manufacture the motors shipped to customers after August 6, 2019. An Abbott representative will contact you to explain how affected motors in your site can be recalibrated.

If you have questions, please contact your local Abbott MCS Clinical Specialist or Clinical & Technical Service +32 2200 6645, which is available 24 hours a day, 7 days a week.

Thank you for your continued support.  
Sincerely,

Lance Mattoon  
Divisional Vice President, Quality  
Abbott Heart Failure

Alexander Goehring  
Director, Quality  
Abbott Heart Failure

FSCA 2019-08 CentriMag Distribution List Switzerland

Serial Number	Description
L06411-0010	CENTRIMAG MOTOR, OUS
L06378-0013	CENTRIMAG MOTOR, OUS
L06378-0014	CENTRIMAG MOTOR, OUS
L06368-0012	CENTRIMAG MOTOR, OUS
L06352-0010	CENTRIMAG MOTOR, OUS
L06352-0011	CENTRIMAG MOTOR, OUS
L06354-0021	CENTRIMAG MOTOR, OUS
L06354-0023	CENTRIMAG MOTOR, OUS
L06367-0021	CENTRIMAG MOTOR, OUS
L05832-0021	CENTRIMAG MOTOR, OUS
L05832-0023	CENTRIMAG MOTOR, OUS
L05833-0002	CENTRIMAG MOTOR, OUS
L05833-0005	CENTRIMAG MOTOR, OUS
L06081-0002	CENTRIMAG MOTOR, OUS
L06081-0006	CENTRIMAG MOTOR, OUS
L05733-0002	CENTRIMAG MOTOR, OUS
L05733-0006	CENTRIMAG MOTOR, OUS