

Recall detail

Type of Product ⁱ	Medical Device
TGA Recall Reference ⁱⁱ	RC-2013-RN-01288-1
Product Name/Description ⁱⁱⁱ	<p>PLUM LifeCare 5000 Series and PLUM XL Family of Infusers</p> <p>Plum LifeCare 5000 List Number: 02507</p> <p>Plum XL List Number: 11555</p> <p>Plum XLM List Number: 11846</p> <p>Plum XLD List Number: 11859</p> <p>ARTG Number: 138109</p>
Recall Action Level ^{iv}	Hospital
Recall Action Classification ^v	Class I
Recall Action Commencement Date ^{vi}	10/12/2013
Responsible Entity ^{vii}	Hospira Pty Limited
Reason / Issue ^{viii}	The door roller assembly on the Plum A Lifecare 5000 Series and Plum XL has the potential to break which can lead to possible unrestricted flow and/or over delivery during the removal of the IV administration set's cassette from the pump.
Recall Action ^{ix}	Recall for Product Correction
Recall Action Instructions ^x	<p>Hospira is requesting hospitals to take the following steps to inspect the door assemble prior to loading the cassette:</p> <ul style="list-style-type: none"> -Open the cassette door by pulling on the lever - Unlatch the cassette door by pushing on the door release tab and pulling the door down. -Visually inspect the door roller pin for any evidence of the damage or door roller misalignment. -Ensure that the door roller spins smoothly with a finger touch. <p>If any door rollers or pins appear loose, broken or missing, Hospira is advising to remove the device from use.</p> <p>Hospira is in the process of retiring the Plum LifeCare 5000 and Plum XL in 2015.</p>
Contact Information ^{xi}	1300 046 774 (Option 1) - Hospira Quality Assurance