

Doc. Ref. FSN 201701 TO WHOM IT MAY CONCERN

## **Urgent: Field Safety Notice ref. FSCA 201701**

POWER DRILL TORQUE LIMITER, code 99-93568 included in the sale configurations Subject:

listed in the table below		
Details of the FSCA		
Date	June 28, 2017	
Reference Contact	Orthofix Customer Service	
	Orthofix Srl Via delle Nazioni, 9 - 37012 Bussolengo (Verona) Italy	
	e-mail: <u>customerservice@orthofix.it</u> – tel.+39 045 6719000 – fax.+39 045 6719380	
Affected Products		
and the control of th	Product code	Product Description
	99-93568	POWER DRILL TORQUE LIMITER
	99-93506	GALAXY UNYCO DIAPHYSEAL TIBIA STERILE KIT
	99-93509	GALAXY UNYCO MINI KIT INSTRUMENTS STERILE
	99-93790	GALAXY UNYCO DIAPHYSEAL FEMUR BOX
	99-93791	GALAXY UNYCO KNEE BRIDGING BOX
	99-93792	GALAXY UNYCO ANKLE BRIDGING BOX - UNILATERAL FRAME
	99-93793	GALAXY UNYCO ANKLE BRIDGING BOX - DELTA FRAME
	99-93794	GALAXY UNYCO DIAPHYSEAL TIBIA BOX
Details of the FSCA  Risk for patient	This is a precautionary action initiated to avoid that potentially defected "power drill torque limiters" cause the disruption of the surgical procedure. The potentially defective "power drill torque limiters" are included in the sale configurations listed above. A defective "power drill torque limiter" may break during use in surgery application. Please see the picture attached to the present FSN which show the power drill torque limiter involved in this action  Disruption of DCO procedure with delay of procedure in emergency circumstances Gradual loss of fixation stability as a consequence of incorrect application of Galaxy Unyco fixator	
Immediate Actions Required – PLEASE REPLY WITHIN JULY 3RD, 2017		
For Distributors	Immediately identify the products in Your warehouse which are involved in this action, quarantine them in your warehouse and communicate the quantity to Orthofix Srl for the replenishment of the additional torque limiters. (see contact details above).  Please ensure that all who received, or who may have received, affected units from You are provided immediately with this Field Safety Notice.  Please fill in the <b>REPLY FORM</b> with all the above information and send to Orthofix.	
For Hospitals	Immediately identify the products in Your warehouse involved in this action, quarantine them in your warehouse and communicate the quantity to your local distributor or directly to Orthofix Srl for the replenishment of the additional torque limiters (see contact details above)	



**Products on patient** 

Orthofix recommends continuing prescribed post-operative activities and follow-up

## Picture of the power drill torque limiter



The undersigned confirms that this notice has been notified to the appropriate Regulatory Agencies.

Respectfully,

Roberto Donadello

Managing Director - VP Operations Intl

Orthofix Srl