REPUBLIC OF LEBANON

MINISTRY OF PUBLIC HEALTH

The Director General



الجمهورية اللبنانية وزارة الصحة العامة

المديسر العسام

رقم المحفوظات: رقام الصادر: ١٠٠٠ ١٠٠٠ ١٠٠٠ ١٠٠٠ ١٠٠٠ بيسروت، في : ٢٠٠٠ ١٠٠٠ بيسروت، في المسادر المساد

جانب نقيب المستشفيات الخاصة في لبنان

الموضوع: إشعار بمتابعة جهاز طبي Liko Standard Slingbar 450

الجهاز المعني بالمتابعة:

- Liko Standard Slingbar 450
- Trade Mark: Hill Rom Inc
- Local Representative:

بناء على التقرير الصادر عن وكالة ال FDA و الذي يشير الى وجود خلل في عمل الصنف المذة

والذي يشير الى وجود خلل في عمل الصنف المذكور أعلاه مما قد يؤثر على سلامة المريض، نرجو منكم تعميم هذه النشرة على جميع المستشفيات المعنية.

مرفق ربطا:

- التقرير الصادر عن وكالة ال FDA لغ:

دائرة البرامج والمشاريع المستشفيات الحكومية

المحقوظات

مديد علم الصحة

FDA Home³ Medical Devices⁴ Databases⁵

Medical & Radiation Emitting Device Recalls



510(k)⁷|Registration & Listing⁸|Adverse Events⁹|Recalls¹⁰|PMA¹¹|Classification¹²|Standards¹²|Inspections¹⁴ CFR Title 2115 Radiation-Emitting Products 16 X-Ray Assembler 17 Medsun Reports 18 CLIA 19 TPLC2

New Search

Back to Search Results



Class 2 Recall Liko Standard Slingbar 450.

Date Posted

December 31, 2012

Recall Number

Z-0622-2013

Product

Liko Standard Slingbar 450. The Standard Slingbar 450 is a versatile sling bar which can be used for most lifting situations. It can be used with different Liko

ceiling and mobile lifts

Code Information

The Like Standard Slingbar 450 accessory has been supplied under multiple product numbers and combined with the sale of mobile lifts. The Standard Slingbar 450 is not serialized and has been distributed between January 1980 and the present. Here are the different Product Numbers in which the Slingbar has been shipped under: Standard Slingbar 450: 20090029, 20190024, 20190041, 31190015, 31290017, 31290043, 3156001, 3156003, 3156007, 3156014, 3156016 31590043, and 5019013. Packaged with Golvo up to April of 2005: 2000001, 2000003, 2000005, 2000006, 2000007, 2000008, 2000009, 2000009CH, 2000009D, 2000009DK, 2000009EU, 2000009F, 2000009FIN, 2000009J, 2000009N, 2000009NL, 2000009UK, 2000009U5, 2000010, 20000100, 20000100K, 2000010EU, 2000010F, 2000010FIN, 2000010H, 2000010J, 2000010N, 2000010NL, 2000010UK, 2000010U5, 2000050, 2000051, 2000061, IN8000, and IN8061. Packaged with Viking up to December of 2004: 2040003, 2040003L, 2040004, 2040005, 2040006. Packaged with Viking up to December of 2004: 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2040003, 2010001, 2010003, 2010003D, 2010003EU, 2010003F, 2010003H, 2010003N, 2010003UK, 2010003US, 2010004, 2010004D, 2010004EU, 2010004F, 2010004H, 2010004N, 2010004UK, 2010004US, 2010005, 2010005EU, 2010005F, 2010005N, 2010005UK, 2010005U5, 2010011, 2010012, 5E2010004, and 5E2010011. Packaged with Caroli lifts up to present: 5011001

Recalling Firm/ Manufacturer

Hill-Rom, Inc. 1069 State Route 46 East Batesville. Indiana 47006-7520

Reason for Recall

Liko/Hill-Rom has received reports from facilities which indicate that serious injuries have been received related to the Standard Sling bar 450. There have been 6 complaints of injury related to the product over the past 32 years (6 out of 838,687,856 estimated patient uses). One of the injuries was associated with a patient during use, four injuries occurred when the slingbar was not

Action

Hill-rom sent an URGENT MEDICAL DEVICE RECALL notification letter dated December 6, 2012. to all affected customers. The letter identified the product the problem and the action needed to be taken by the customer. Customers were requested to please read, fill in completely, and return the Response Form to Hill-Rom immediately. This information will be compiled and reported to the applicable regulatory governing bodies. If we do not receive your response we will be required to contact you asking for your response. Continue to follow safe lifting practices, and do not allow unauthorized persons, especially children, to play around or operate the lift. If you have any questions concerning this Customer Safety Notification, please contact Hill-Rom Technical Support at 800-445-3720.

Quantity in Commerce 261 units

Distribution

Worldwide Distribution -- US (nationwide) including the states of AR. AZ. CA, CO, FL, GA, HI, IA IL, IN, KS, KY, MA, ME, MI, MN, MO, MS, NC, NE, NJ, NM, NV, NY, OK, OR, PA, TN, TX, UT, WA, WV, and WY., and the country Canada, We have not yet defined our European or International facilities at this time

Links on this page:

- 1. http://www.addthis.com/bookmark.php?u508=true&v=152&username=fdamain
- 2. http://www.addthis.com/bookmark.php
- 3. http://www.fda.gov/default.htm
- http://www.fda.gov/MedicalDevices/default.htm
- http://www.fda.gov/MedicalDevices/DeviceRegulationand/Guidance/Databases/defauit.htm
- 6. /scripts/cdrh/devicesatfda/index.cfm
- 7. /scripts/cdrh/cfdocs/cfPMN/pmn.cfm
- 8. /scripts/cdrh/cfdocs/cfRL/rl.cfm
- 9. /scripts/carh/cfdocs/cfMAUDE/TextSearch.cfm
- 10. /scripts/cdrh/cfdocs/cfRES/res.cfm
- 11. /scripts/cdrh/cfdocs/cfPMA/pma.cfm
- 12. /scripts/cdrh/cfdocs/cfPCD/classification.cfm